

Facility Summary in SHERIDAN County in the City of MEDICINE LAKE

Location: MEDICINE LAKE SCHOOL DIST 7
1 YOUNG ST
MEDICINE LAKE, MT 59247 SHERIDAN
Contact: (406) 789-2211

Sys Fac ID: 46-01122
Last Inspected On: 1/16/2014
Operating Permit Renewal Date: 1/21/2017

Owners/Operators: School Dist 7 Medicine Lake, Owner (406)-789-2211 PO BOX 265
MEDICINE LAKE MT 59247-0265
Mike Olson, UST Class A Operator
James Simoneau, UST Class A Operator
Mike Olson, UST Class B Operator
James Simoneau, UST Class B Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|---------------------------------|---------------------------------|------------------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 2 | 24 | 8/1/1991 | Steel Clad | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 1603 | | 1/27/2012 | Double-Walled | Double-Walled | Yes |
| Currently in Use | | | Not Required | U.S. Suction | Not Applicable |
| Heating Oil | | 1/16/2014 | Continuous Interstitial Monitor | Continuous Interstitial Monitor | |
| 10,066 | | | OPW 1500 , OPW | | |

Facility Summary in SHERIDAN County in the City of MEDICINE LAKE

Location: LAKE PIT STOP
MT HIGHWAY 16 & MAIN ST
MEDICINE LAKE, MT 59247 SHERIDAN
Contact: Donald Johnson, (406) 963-2286

Sys Fac ID: 46-01127
Last Inspected On: 1/5/2016
Operating Permit Renewal Date: 3/30/2019

Owners/Operators: Lake Pit Stop LLC, Owner (406)-789-2242 PO BOX 173
MEDICINE LAKE MT 59247
Lake Pit Stop, Operator (406)-789-2242 HWY 16 & MAIN
MEDICINE LAKE MT 59247
Robert Herman, UST Class A Operator
Chanel Johnson, UST Class A Operator
Chanel Johnson, UST Class B Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|------------------------------------|---------------------------------|-----------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 6 | 18 | 10/1/1997 | Unknown | Flexible Plastic | |
| 2323 | Yes | 10/15/2013 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Not Applicable |
| Gasoline | | | Deferred | Continuous Interstitial Monitor | |
| 15,000 | | 4/24/2015 | Other , Other | | |
| 7 | 18 | 10/1/1997 | Unknown | Flexible Plastic | |
| 2324 | Yes | 10/15/2013 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Not Applicable |
| Diesel | | | Deferred | Continuous Interstitial Monitor | |
| 12,000 | | 4/24/2015 | Other , Other | | |
| 8 | 18 | 10/1/1997 | Unknown | Flexible Plastic | |
| 2325 | Yes | 10/15/2013 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Not Applicable |
| Diesel | | | Deferred | Continuous Interstitial Monitor | |
| 12,000 | | 4/24/2015 | Other , Other | | |
| 9 | 18 | 10/1/1997 | Unknown | Flexible Plastic | |
| 2326 | Yes | 10/15/2013 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Not Applicable |
| Gasoline | | | Deferred | Continuous Interstitial Monitor | |
| 8,000 | | 4/24/2015 | Other , Other | | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: SHERIDAN MEMORIAL HOSPITAL
440 W LAUREL AVE
PLENTYWOOD, MT 59254 SHERIDAN
Contact: Paul Beck, (406) 765-1420

Sys Fac ID: 46-00795
Last Inspected On: 1/16/2014
Operating Permit Renewal Date: 6/3/2017

Owners/Operators: Sheridan Memorial Hospital, Owner (406)-765-1420 440 W LAUREL AVE
PLENTYWOOD MT 59254-1596
Murvin Anderson, UST Class A Operator
Mark A Brensdal, UST Class A Operator
Michael Cox, UST Class A Operator
Athena Gardenier, UST Class B Operator
Michael Cox, UST Class B Global Operator
Athena Gardenier, UST Class B Global Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|-------------------------------|---------------------------------|------------------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 3 | 17 | 10/1/1998 | Steel Clad | Flexible Plastic | Flapper Valve (Auto Shutoff) |
| 1918 | | 3/19/2014 | Double-Walled | Double-Walled | Yes |
| Currently in Use | | | Not Required | U.S. Suction | Not Applicable |
| Heating Oil | | | Manual Interstitial Monitor | Continuous Interstitial Monitor | |
| 8,000 | | | | | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: AUTO TECH SERVICES
327 W 1ST AVE
PLENTYWOOD, MT 59254 SHERIDAN
Contact: James Kibbe, (406) 765-1180

Sys Fac ID: 46-01524
Last Inspected On: 12/18/2015
Operating Permit Renewal Date: 6/8/2019

Owners/Operators: Farmers Union Oil Co Plentywood, Owner (406)-765-1171 301 W 1ST AVE
PLENTYWOOD MT 59254-1802
James Kibbe, UST Class A Operator
L James Kibbe, UST Class A Operator
James Kibbe, UST Class B Global Operator
L James Kibbe, UST Class B Global Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|-------------------------------|-------------------------------|------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 8 | 26 | 12/10/1989 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | High Level Alarm |
| 1114 | | | None | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Galvanic |
| Diesel | | 12/18/2015 | Automatic Tank Gauging 0.2 | Deferred | |
| 4,000 | | | TLS-450 , Veeder Root | | |
| 9 | 26 | 12/10/1989 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | High Level Alarm |
| 1115 | | | None | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Galvanic |
| Gasoline | | 12/18/2015 | Automatic Tank Gauging 0.2 | Deferred | |
| 4,000 | | | TLS-450 , Veeder Root | | |
| 10 | 26 | 12/10/1989 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | High Level Alarm |
| 1116 | | | None | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Galvanic |
| Gasoline | | 12/18/2015 | Automatic Tank Gauging 0.2 | Deferred | |
| 10,000 | | | TLS-450 , Veeder Root | | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: KUM AND GO STORE 808
211 W 1ST AVE
PLENTYWOOD, MT 59254 SHERIDAN
Contact: Gary D Reynolds, (406) 765-2847

Sys Fac ID: 46-05200
Last Inspected On: 8/28/2014
Operating Permit Renewal Date: 9/10/2017

Owners/Operators: Krause Gentle Corp, Owner (515)-226-0128 MARC HYLAND
6400 WESTOWN PKWY
WEST DES MOINES IA 50266-7709

Christopher Bergman, UST Class A Operator
Mike Simpson, UST Class A Operator
Christopher Bergman, UST Class B Global Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|------------------------------------|--|------------------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 3 | 33 | 12/1/1982 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 1498 | | | Lined Interior/Impressed Current | Double-Walled | Yes |
| Currently in Use | | | Electronic Line Leak Detector | Pressurized | Impressed Current |
| Diesel | | 8/28/2014 | Automatic Tank Gauging 0.2 | Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2 | |
| 6,000 | | 8/28/2014 | TLS-350/Gilbarco EMC , Veeder Root | Continuous Interstitial Monitor | |
| 4 | 28 | 1/1/1988 | Bare Steel | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 4358 | | | Impressed Current | Double-Walled | Yes |
| Currently in Use | | | Electronic Line Leak Detector | Pressurized | Impressed Current |
| Gasoline | | 8/28/2014 | Automatic Tank Gauging 0.2 | Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2 | |
| 12,000 | | 8/28/2014 | TLS-350/Gilbarco EMC , Veeder Root | Continuous Interstitial Monitor | |
| 5 | 28 | 1/1/1988 | Bare Steel | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 1500 | | | Impressed Current | Double-Walled | Yes |
| Currently in Use | | | Electronic Line Leak Detector | Pressurized | Impressed Current |
| Gasoline | | 8/28/2014 | Automatic Tank Gauging 0.2 | Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2 | |
| 12,000 | | 8/28/2014 | TLS-350/Gilbarco EMC , Veeder Root | Continuous Interstitial Monitor | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: SHERIDAN COUNTY
100 W LAUREL AVE
PLENTYWOOD, MT 59254 SHERIDAN

Sys Fac ID: 46-06278

Last Inspected On: 1/2/2014

Operating Permit Renewal Date: 6/18/2017

Contact: Gary Bartnes, (406) 765-2310

Owners/Operators: Sheridan County Sanitarian, Owner (406)-765-2310 100 W LAUREL AVE
PLENTYWOOD MT 59254-1647

Gary Bartnes, UST Class A Operator
Jerry Hendrickson, UST Class A Operator
Gary Bartnes, UST Class B Global Operator
Jerry Hendrickson, UST Class B Global Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|---------------------------------|-----------------------------|------------------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 2 | 20 | 9/1/1995 | Steel Clad | Flexible Plastic | Flapper Valve (Auto Shutoff) |
| 1911 | | 3/25/2014 | Double-Walled | Double-Walled | Yes |
| Currently in Use | | | Auto Dialer | Gravity Feed | Galvanic |
| Heating Oil | | 1/5/2011 | Continuous Interstitial Monitor | MLLD Line Tightness Testing | |
| 10,000 | | 4/30/2014 | | | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: SHERIDAN COUNTY SHOP
MT HIGHWAY 16 E
PLENTYWOOD, MT 59254 SHERIDAN
Contact: Walt Heppner, (406) 765-1221

Sys Fac ID: 46-06279
Last Inspected On: 1/2/2014
Operating Permit Renewal Date: 2/19/2017

Owners/Operators: Sheridan County Sanitarian, Owner (406)-765-2310 100 W LAUREL AVE
PLENTYWOOD MT 59254-1647
DELLAS CHRISTENSEN, UST Class A Operator
DELLAS CHRISTENSEN, UST Class B Global Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|-------------------------------|-------------------------------|------------------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 5 | 26 | 1/1/1990 | Steel Clad | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 1912 | | | Double-Walled | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Galvanic |
| Gasoline | | 1/5/2011 | Manual Interstitial Monitor | Deferred | |
| 10,000 | | | | | |
| 6 | 26 | 1/1/1990 | Steel Clad | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 1913 | | | Double-Walled | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Galvanic |
| Diesel | | 1/5/2011 | Manual Interstitial Monitor | Deferred | |
| 10,150 | | | | | |
| 7 | 26 | 1/1/1990 | Steel Clad | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 1914 | | | Double-Walled | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Galvanic |
| Diesel | | 1/5/2011 | Manual Interstitial Monitor | Deferred | |
| 10,150 | | | | | |
| 8 | 26 | 1/1/1990 | Steel Clad | Fiberglass Reinforced Plastic | |
| 1915 | | | Double-Walled | None | Yes |
| Currently in Use | | | Not Required | U.S. Suction | Galvanic |
| Waste Oil | | 1/5/2011 | Manual Interstitial Monitor | MLLD Line Tightness Testing | |
| 1,002 | | 4/29/2014 | | | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: FARMERS UNION OIL CO PLENTYWOOD
301 W 1ST AVE
PLENTYWOOD, MT 59254 SHERIDAN

Sys Fac ID: 46-06801

Last Inspected On: 7/8/2015

Operating Permit Renewal Date: 8/23/2018

Contact: Jeffrey P Schaefer, (406) 765-1171

Owners/Operators: Farmers Union Oil Co Plentywood, Owner

(406)-765-1171

301 W 1ST AVE

PLENTYWOOD MT 59254-1802

L James Kibbe, UST Class A Operator

L James Kibbe, UST Class B Global Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|------------------------------------|---------------------------------|------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 8 | 19 | 6/1/1996 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | Positive Shutoff |
| 1038 | | 6/13/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Galvanic |
| Gasoline | | 6/3/2015 | Automatic Tank Gauging 0.2 | Continuous Interstitial Monitor | |
| 20,000 | | | Gilbarco EMC Basic , Gilbarco | | |
| 9 | 19 | 6/1/1996 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | Positive Shutoff |
| 1039 | | 6/13/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Galvanic |
| Diesel | | 6/3/2015 | Automatic Tank Gauging 0.2 | Continuous Interstitial Monitor | |
| 20,000 | | | Gilbarco EMC Basic , Gilbarco | | |
| 10 | 19 | 6/1/1996 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | Positive Shutoff |
| 1040 | | 6/13/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Galvanic |
| Gasoline | | 6/3/2015 | Automatic Tank Gauging 0.2 | Continuous Interstitial Monitor | |
| 12,000 | | | Gilbarco EMC Basic , Gilbarco | | |
| 11 | 19 | 6/1/1996 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | Positive Shutoff |
| 1041 | | 6/13/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Galvanic |
| Diesel | | 6/3/2015 | Automatic Tank Gauging 0.2 | Continuous Interstitial Monitor | |
| 12,000 | | | Gilbarco EMC Basic , Gilbarco | | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: FARMERS UNION OIL CO PLENTYWOOD
 301 W 1ST AVE
 PLENTYWOOD, MT 59254 SHERIDAN
Contact: Jeffrey P Schaefer, (406) 765-1171

Sys Fac ID: 46-06801
Last Inspected On: 7/8/2015
Operating Permit Renewal Date: 8/23/2018

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|------------------------------------|---------------------------------|------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 12 | 19 | 6/1/1996 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | Positive Shutoff |
| 1042 | | 6/13/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Galvanic |
| Diesel | | 6/3/2015 | Automatic Tank Gauging 0.2 | Continuous Interstitial Monitor | |
| 12,000 | | | Gilbarco EMC Basic , Gilbarco | | |
| 13 | 19 | 6/1/1996 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | Positive Shutoff |
| 1043 | | 6/13/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Galvanic |
| Diesel | | 6/3/2015 | Automatic Tank Gauging 0.2 | Continuous Interstitial Monitor | |
| 8,000 | | | Gilbarco EMC Basic , Gilbarco | | |
| 14 | 19 | 6/1/1996 | Cathodically Protected Steel | Fiberglass Reinforced Plastic | Positive Shutoff |
| 1044 | | 6/13/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Continuous Interstitial Monitoring | Pressurized | Galvanic |
| Diesel | | 6/3/2015 | Automatic Tank Gauging 0.2 | Continuous Interstitial Monitor | |
| 8,000 | | | Gilbarco EMC Basic , Gilbarco | | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: MILLER OIL CO INC E RAILROAD AVE
416 WEST RAILROAD AVE
PLENTYWOOD, MT 59254 SHERIDAN
Contact: Matt Miller, (406) 765-2852

Sys Fac ID: 46-08609
Last Inspected On: 10/27/2015
Operating Permit Renewal Date: 3/4/2019

Owners/Operators: Miller Oil Co Inc Culbertson, Owner (406)-787-5230 PO BOX 408
CULBERTSON MT 59218-0408
Kevin Miller, UST Class A Operator
Kevin Miller, UST Class B Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|------------------------------------|---|-------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 1 | 48 | 4/8/1967 | Bare Steel | Fiberglass Reinforced Plastic | |
| 1617 | Yes | 6/18/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Electronic Line Leak Detector | Pressurized | Not Applicable |
| Diesel | | | Deferred | Automatic Tank Gauging 0.2, ELLD Line Tightness Testing | |
| 12,048 | | 8/5/2009 | TLS-350/Gilbarco EMC , Veeder Root | Continuous Interstitial Monitor | |
| 2 | 54 | 4/7/1961 | Bare Steel | Fiberglass Reinforced Plastic | |
| 1618 | Yes | 6/18/2015 | None | Double-Walled | No |
| Currently in Use | | | Electronic Line Leak Detector | Pressurized | Impressed Current |
| Gasoline | | 8/8/2006 | Deferred | Automatic Tank Gauging 0.2, ELLD Line Tightness Testing | |
| 5,327 | | 8/5/2009 | TLS-350/Gilbarco EMC , Veeder Root | Continuous Interstitial Monitor | |
| 3 | 48 | 4/8/1967 | Bare Steel | Fiberglass Reinforced Plastic | |
| 1619 | Yes | 6/18/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Electronic Line Leak Detector | Pressurized | Impressed Current |
| Gasoline | | 8/8/2006 | Deferred | Automatic Tank Gauging 0.2, ELLD Line Tightness Testing | |
| 14,848 | | 8/5/2009 | TLS-350/Gilbarco EMC , Veeder Root | Continuous Interstitial Monitor | |
| 4 | 47 | 4/7/1968 | Bare Steel | Fiberglass Reinforced Plastic | |
| 1620 | Yes | 6/18/2015 | None | Double-Walled | Yes |
| Currently in Use | | | Electronic Line Leak Detector | Pressurized | Impressed Current |
| Diesel | | 8/8/2006 | Deferred | Automatic Tank Gauging 0.2, ELLD Line Tightness Testing | |
| 14,773 | | 8/5/2009 | TLS-350/Gilbarco EMC , Veeder Root | Continuous Interstitial Monitor | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: MONTANA PIONEER MANOR INC
605 SHERIDAN ST
PLENTYWOOD, MT 59254 SHERIDAN

Sys Fac ID: 46-10679

Last Inspected On: 1/31/2013

Operating Permit Renewal Date: 6/4/2016

Contact: Ervin Steitzer, (406) 765-1362

Owners/Operators: Montana Pioneer Manor Inc, Owner (406)-765-1362 605 SHERIDAN ST
PLENTYWOOD MT 59254-1715

Charles Archer, UST Class A Operator
Diane Archer, UST Class A Operator
Ervin Steltzer, UST Class A Operator
Charles Archer, UST Class B Operator
Diane Archer, UST Class B Operator
Ervin Steltzer, UST Class B Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|-------------------------------|--------------------------|------------------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 1 | 19 | 5/1/1996 | Steel Clad | Flexible Plastic | Flapper Valve (Auto Shutoff) |
| 1673 | | 8/16/2013 | Double-Walled | Double-Walled | Yes |
| Currently in Use | | | Not Required | Safe Suction | Not Applicable |
| Heating Oil | | | Manual Interstitial Monitor | Not Listed | |
| 10,000 | | | | | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: SHERWOOD AIRPORT
100 W LAUREL AVE
PLENTYWOOD, MT 59254 SHERIDAN

Sys Fac ID: 46-12330

Last Inspected On: 1/2/2014

Operating Permit Renewal Date: 3/10/2017

Contact: Milt Hovland, (406) 765-2310

Owners/Operators: Sheridan County Sanitarian, Owner (406)-765-2310 100 W LAUREL AVE
PLENTYWOOD MT 59254-1647

Gary Bartnes, UST Class A Operator
Jerry Hendrickson, UST Class A Operator
Gary Bartnes, UST Class B Global Operator
Jerry Hendrickson, UST Class B Global Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------------|-----|-------------------|-------------------------------|-------------------------------|------------------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 1 | 27 | 1/1/1989 | Steel Clad | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 1916 | | | Double-Walled | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Galvanic |
| Gasoline | | 1/5/2011 | Not Listed | Deferred | |
| 10,000 | | | | | |
| 2 | 27 | 1/1/1989 | Steel Clad | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 1917 | | | Double-Walled | None | Yes |
| Temporarily Out of Use | | | Not Required | Safe Suction | Galvanic |
| Gasoline | | 1/5/2011 | Not Listed | Deferred | |
| 10,000 | | | | | |

Facility Summary in SHERIDAN County in the City of PLENTYWOOD

Location: MNLC INC CAN AM STORES
203 RAYMOND RD
PLENTYWOOD, MT 59254 SHERIDAN

Sys Fac ID: 46-12667

Last Inspected On: 8/20/2015

Operating Permit Renewal Date: 11/13/2018

Contact: Lance Chandler, (406) 765-2983

Owners/Operators: MNLC Inc Can Am Stores, Owner (406)-765-2121 203 RAYMOND RD
PLENTYWOOD MT 59254-1545
Lance Chandler, UST Class A Operator
Lance Chandler, UST Class B Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|-------------------------------|-------------------------------|------------------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 1 | 24 | 7/1/1991 | Steel Clad | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 2954 | | | Double-Walled | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Not Applicable |
| Gasoline | | | Manual Interstitial Monitor | Not Listed | |
| 10,000 | | | | | |
| 2 | 24 | 7/1/1991 | Steel Clad | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 2955 | | | Double-Walled | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Not Applicable |
| Diesel | | | Manual Interstitial Monitor | Not Listed | |
| 10,000 | | | | | |

Facility Summary in SHERIDAN County in the City of RESERVE

Location: JACKS SERVICE
101 MAIN ST
RESERVE, MT 59258 SHERIDAN

Sys Fac ID: 46-02103

Last Inspected On: 1/16/2014

Operating Permit Renewal Date: 1/21/2017

Contact: Jack Schmidt, (406) 286-5465

Owners/Operators: Jacks Service Reserve, Owner (406)-286-5276 PO BOX 165
RESERVE MT 59258-0165
Jack Schmidt, UST Class A Operator
Jack Schmidt, UST Class B Operator

| Tank Id | Age | Installed | Tank Material of Construction | Piping Material | Overfill Types |
|------------------|-----|-------------------|-------------------------------|-------------------------------|------------------------------|
| Tag Number | AST | Sump Tightness | Secondary Option | Secondary Option | Spill Protected |
| Status | | Inventory Control | Catastrophic L.D. Type 3.0 | Piping Type | CP Met Types |
| Product | | Tank/Pipe CP | Tank Detection | Primary Pipe Detection | Vapor Recovery |
| Capacity | | Line Tightness | ATG Type | Secondary Pipe Detection | Energy Act |
| 3 | 24 | 5/21/1991 | Steel Clad | Fiberglass Reinforced Plastic | Flapper Valve (Auto Shutoff) |
| 4733 | | | Double-Walled | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Not Applicable |
| Gasoline | | | Manual Interstitial Monitor | Deferred | |
| 2,000 | | | | | |
| 5 | 15 | 7/27/2000 | Steel Clad | Flexible Plastic | Flapper Valve (Auto Shutoff) |
| 4213 | | | Double-Walled | None | Yes |
| Currently in Use | | | Not Required | Safe Suction | Not Applicable |
| Diesel | | | Manual Interstitial Monitor | Deferred | |
| 2,000 | | | | | |